

## Gearhead to Motor Mounting Information

### MOUNTING INSTRUCTIONS

- Using the screws provided, bolt the mounting bracket to the input end of the gearhead ratio unit.
- Slide the motor shaft sleeve into the input clamp and align the slot in the sleeve with the slot in the clamp.
- Rotate the clamp to align the mounting bracket access holes with the clamping bolts.
- Place the motor on a solid work surface with the output shaft pointing up. Slide the assembled gearhead onto the motor shaft.
- Using a torque wrench, tighten the clamp bolts to the pretorque values listed below.
- Using the screws provided, bolt the gearhead to the motor.
- Using an alternating pattern, gradually tighten the clamp bolts until you reach the final tightening torque listed below.

**Clamp Bolt Tightening Torques**

Gearhead Frame Size	Pretightening Torque		Final Tightening Torque	
	lb. in.	N • m	lb. in.	N • m
NEMA 23	2	0.2	39	4.4
NEMA 34	4	0.4	76	8.5
NEMA 42	16	1.8	316	36
Metric 60	2	0.2	39	4.4
Metric 90	4	0.4	76	8.5
Metric 115	16	1.8	316	36

### USEFUL FORMULAS

$$\text{The maximum output HP of Gearhead} = \frac{(\text{Maximum continuous torque}) \times (\text{Maximum rated output rpm})}{63025}$$

$$\text{The maximum allowable output HP of the motor} = \frac{\text{The maximum output HP of gearhead}}{0.90 \text{ (single stage) or } 0.85 \text{ (double stage)}}$$

$$\text{Effective inertia} = \frac{\text{load inertia}}{(\text{gear ratio})^2} + \text{gearhead}^A \text{ inertia} + \text{pinion}^A \text{ inertia}$$

**For very fast response,** the effective inertia should be one to three times larger than the motor inertia (including the pinion).

**For acceptably fast response,** the effective inertia should be less than ten times larger than the motor inertia (including the pinion).

<sup>A</sup>Inertia values shown in this catalog include both the gearhead and pinion values.